A Safe Workplace A Workplace Safety and Health Manual for Your Community

	*	~		
	Section:	Rules Procedures, Practices		Page 1 of 1
	III-C	and Guidelines	Approved By: Harvey Bostrom	
	Subject:	Pipefitting	Effective: April 01, 2005	
	G-3		Revised: April 1, 2011	

PPE Required: Steel-toe boots, safety glasses or face shield, hard hat, gloves, coveralls, fire extinguishers, first aid kit

Preparation:

- 1. Ensure area is free of toxic gases. Use an appropriate and calibrated gas detector for atmosphere testing. Wear SCBA if the atmosphere is or could become hazardous.
- 2. Secure the area.
- 3. Ensure all tools are clean and in proper working condition and that all repair parts are handy.

Steps:

- 1. Set up barricades if required using *Barricade Procedure* (section III-C-G6).
- 2. Isolate section of pipe to be repaired by slowly closing valves. Lock valves in closed position. Refer to part 16 *The Manitoba Workplace Safety and Health Act and Regulations* and SWP G-11 in Section III-E of ASW manual on lockout.
- 3. Disassemble pipe, making sure there is no pressure in the pipe before you start removing unions or flanges.
- 4. As work is underway, monitor closely to ensure there are no gasses released into the area.
- 5. Ensure other workers are available to assist when required.
- 6. If pipe cutting is required the pipe should be cut away from work area. Ensure pipe is secured with clamps or vise prior to cutting.
- 7. Ensure Teflon tape is used on threaded joints of different material.
- 8. When fusing solvent weld joints, ensure there is adequate ventilation.
- 9. Fusing solvent weld joints must be performed by trained personnel.
- 10. Clean work area.
- 11. Remove locks and slowly release pressure into the new section and test each joint for leaks.
- 12. Remove barricades using Barricade Procedure (Section III-C-G6).