



Carrier Convictions

Manitoba Infrastructure



	Generic Code Description	Section	Ticket Number	Viol. Juris.	Violation Date	Plate Number	Weight	Acc. Inv.	Driver Licence #	Licence Juris.	
A short summary of the conviction.	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE31	МВ	19/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	The driver license number of the
· · · · · · · · · · · · · · · · · · ·	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE32	МВ	18/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	individual that was driving at the time of the violation.
The jurisdiction where the violation occurred.	CONTROL DEVICE	HTA 85 RI	SAMPLE33	МВ	17/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	
-	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE34	МВ	16/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	How many points are going on your carrier profile as a result of this
The Common Offense Notice number	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE35	МВ	15/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	conviction.
,	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE36	МВ	14/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	MB	The date on which the violation took place
The section of the HTA or other regulation in	CONTROL DEVICE	HTA 85 RL	SAMPLE37	МВ	13/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	
which the carrier was in violation.	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE38	МВ	12/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	The jurisdiction in which the diver was licensed.
	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE39	МВ	11/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	The license plate number of the vehicle
	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE310	МВ	10/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	MB	that was either ticketed or carrying the driver
	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE311	МВ	9/Feb/2015	ZZZ001	3	N	DOE**JH3 02C1	МВ	that was ticketed.
	FAIL TO OBEY TRAFFIC CONTROL DEVICE	HTA 85 RL	SAMPLE312	МВ	8/Feb/2015	ZZZ001		N	DOE**JH3 02C1	МВ	Describes whether there was an investigation.
							36				

Carrier Convictions by Offence Category

Manitoba Infrastructure



·····	Generic Code	Description	# of Convictions	Weight	Weighted Count	Percentage	
Category in which convictions are grouped.	DRIVERS LIABILITY	DRIVER'S LIABILI	TY				
	VIOLATION INVOLVING THE USE ALLOWING MORE PASSENGERS AVAILABLE		1	2	2.00	100%	
	Total	s for DRIVERS LIABILITY	1		2	-0 -0	
(Percent of Totals	1%		2%		
Description of each conviction that is	DRIVING	DRIVING				-	
common to all jurisdictions. All	DISOBEY AMBER LIGHT		1	3	3.00	5%	
jurisdictions use common descriptions	DRIVING AT SPEED GREATER TH AND PRUDENT; SPEED TOO FAS		_1	2	2.00	3%	The total of each particular conviction
for all convictions.	DRIVING WITHOUT DUE CARE AN WITHOUT REASONABLE CONSIDUSING ROADWAY		2	3	6.00	9%	accumulated by all the carrier's drivers over the past 24 months.
Points from 1-5 are	EXCEED 60 KM/HOUR WHEN PAS WORKER	SSING HIGHWAY	4	2	8.00	13%	***************************************
assigned to each type of	EXCEEDING POSTED SPEED LIM	IT	4	1	4.00	6%	
offence depending on severity. Not the same	FAIL TO OBEY TRAFFIC CONTRO	DL DEVICE	6	3	18.00	28%	Number of convictions
as the demerit points on	FOLLOWING VEHICLE TOO CLOS	SELY	1	3	3.00	5%	multiplied by the weight
an individual's driver licence.	IMPROPER LANE OR LOCATION		1	2	2.00	3%	of each offence
(IMPROPER, DANGEROUS OR ILL CROSSING A MEDIAN STRIP OR		2	2	4.00	6%	······································
	SPEEDING 1-10 KM/HOUR OVER	POSTED LIMIT	1	1	1.00	2%	Percentage of each
	SPEEDING 11-20 KM/HOUR OVER	R POSTED LIMIT	3	1	3.00	5%	conviction within that category, with the total
	SPEEDING 21-30 KM/HOUR OVER	R POSTED LIMIT	3	2	6.00	9%	in each category being
	SPEEDING 31-40 KM/HOUR OVER	R POSTED LIMIT	1	0	0.00	0%	100%. Used to calculate Performance Threshold.
	SPEEDING 31-40 KM/HOUR OVER	R POSTED LIMIT	1	3	3.00	5%	
Total number of convictions and	USING HAND-OPERATED ELECTED DRIVING	RONIC DEVICE WHILE	1	1	1.00	2%	Domonton of total
weighted points within each category.		Totals for DRIVING	32		64		Percentage of total convictions represented
		Percent of Totals	48%		51%		by that category. Cumulative total across all categories is 100%.



	Report #	Level	Prov. State	Inspection Location	Inspection Date	Power Unit Plate	Driver Name	Weight Result	,
CVSA report number	MBTEST301	1	МВ	Somewhere	19/Feb/2015	ZZZ001	DOE, JOHN H	3 COS	How many points were attributed to the carrier profile as
	MBTEST302	1	MB	Somewhere	18/Feb/2015	222001	DOE, JOHN H	3 COS	a result of the inspection findings.
Level of inspection; can be a Level 1 (full), Level 2 (walk	MBTEST303	1	MB	Somewhere	17/Feb/2015	222001	DOE, JOHN H	3 COS	Pass = 0, Fail = 0. Out of Service (OOS) = 3.
around / driver and truck/trailer), Level	MBTEST304	1	MB	Somewhere	16/Feb/2015	222001	DOE, JOHN H	3 COS	
3 (driver only) Level 4 (equipment specific) or Level 5	MBTEST305	1	MB	Somewhere	15/Feb/2015	222001	DOE, JOHN H	3 COS	When the inspection took place.
(facility or site inspection, driver and truck/trailer).	MBTEST306	-1	МВ	Somewhere	14/Feb/2015	ZZZ001	DOE, JOHN H	3 COS	<i>:</i>
	MBTEST307	1	МВ	Somewhere	13/Feb/2015	222001	DOE, JOHN H	3 COS	The name of the driver that was driving the truck or
Jurisdiction in which the inspection took place.	MBTEST308	1	MB	Somewhere	12/Feb/2015	222001	DOE, JOHN H	3 COS	truck tractor at the time of inspection.
place.	MBTEST309	1	MB	Somewhere	11/Feb/2015	ZZZ001	DOE, JOHN H	3 COS	
	MBTEST310	1	МВ	Somewhere	10/Eeb/2015	777001	DOE, JOHN H	cos	Where within jurisdiction the
License plate	MBTEST311	1	MB	Somewhere	9/Feb/2015	<i>ZZZ</i> 001	DOE, JOHN H	3 COS	inspection occurred.
number of the truck or truck tractor	MRTEST312	1	MR	Somewhere	8/Feh/2015	222001	DOE, JOHN H	3 COS	
inspected.		New Year						36	

Carrier CVSA Inspection Defects by Category

Manitoba Infrastructure



29

Total for Category:

Defect Description Count One of 14 CVSA BRAKES Inspection categories in AUDIBLE AIR LEAK, PUSH ROD 15 which critical defects CHAMBERS, RESERVOIR, COMPRESSOR 64 are grouped. FLUID LEAKAGE, LOW LEVEL, LOW PEDAL, WARNING LIGHT HOSE, LINES, COUPLING, VALVES LINING, DRUMS, DISCS SLACK ADJUSTER, CAM SHAFT 84 Total for Category: COUPLING DEVICES Cumulative total of each FIFTH WHEEL ASSEMBLY - UPPER / LOWER CRACKS 1 defect during all CVSA inspections for that Total for Category: carrier over the past 24 DANGEROUS GOODS months. DANGEROUS GOODS Total for Category: EMERGENCY EXITS / ELECTRICAL (BUSES) **EMERGENCY EXITS** Total for Category: **EXHAUST** LEAK, LOCATION 1 1 Total for Category: FRAME Breakdown of defects CROSS MEMBER-BROKEN, SAGGING 1 within each of the 14 Total for Category: categories. LIGHTING EQUIPMENT HEADLAMPS, TAIL LIGHTS, SIGNAL, BRAKE 47 Cumulative total of all PROJECTING LOAD LAMPS, CLEARANCE defects within each 49 Total for Category: category accumulated LOAD SECUREMENT during all CVSA SPARE TIRE, DEFECTIVE TIE-DOWNS 66 inspections for that 66 carrier over the past 24 Total for Category: months STEERING MECHANISM STEERING WHEEL, COLUMN, GEAR BOX 4 4 Total for Category: SUSPENSION AXLE PARTS - CRACKED, LOOSE, BROKEN, MISSING 7 7 Total for Category: TIRES WORN, CUT, FLAT, MIXED, CRACKED, UNDER-SIZED, INFLATED 29

Carrier Accidents



	<u></u>								
	Case #	Plate #	Accident Date	Accident Severity	Accident Jurisdiction	# of Injured	# of Fatalities	Weight	Driver Licence #
Identification number	401631501060005	PCF550	6/Jan/2015	PROPERTY	QC	0	0	0	XX
	20144484260C01	PCV532	9/Dec/2014	PROPERTY	AB	0	0	0	EBINGJ*139PJ
	NYSP19375910	PCE862	10/Nov/2014	•	NY	0	0	0	F25557854571129
	334400	PBP193	30/Sep/2014	PROPERTY	MB	0	0	0	ARVINA*091BB
Plate number of the	2014045285202	PCS934	24/Sep/2014	PROPERTY	AB	0	0	0	BHAGTJS091Q8
ommercial vehicle	310923	PCT451	17/Jul/2014	PROPERTY	327	0	0	0	READ*DM521KE
oower unit (truck or ruck tractor) involved.	40172573	PCS948	1/May/2014	PROPERTY		0	0	2	F06622976690716
rack tractory involved.	299371	PCT438	29/Mar/2014	PROPERTY		0	0	0	VERHAJT233PE
	40122216	PCH692	24/Mar/2014	1,0000		0	0	2	S44903080870507
	3540L000000000	N. S. ASSOCIATION	OR CAROLINA COURSE OF	PROPERTY	1500	-	703	**	
	The second of	PCH676	21/Mar/2014		MI	0	0		KUSHLI*207NU
Date in which accident occurred	401461403140003		14/Mac/2014	PROPERTY		0	0	0	
occurred	MN0140900239	PBP479	11/Mar/2014	INJURY	MN	0	0	0	ADEYAOS271DZ
	1820082.2	PCT433	E/Mar/2014	PROPERTY	SK	O	0	n.	15759266B
	271091	PCH676	22/Feb/2014	PROPERTY	MB	0	0	0	KUSHLI*207NU
	2014030734401	PCH718	14/Jan/2014	PROPERTY	AB	0	0	0	00257000
	R444924701	PBP362	11/Jan/2014	PROPERTY	BC	0	0	0	06967251
roperty (least severe),	264787	PBE491	7/Jan/2014	PROPERTY	MB	0	0	0	SIDHUNS125NZ
jury or fatality (most	405411401060007	PCE512	6/Jan/2014	PROPERTY	QC .	0	0	0	
evere)	9094501	PCN883	15/Dec/2013	PROPERTY	NS	0	0	2	802989
	30660089	PCG497	7/Nov/2013	PROPERTY	ON	0	0	0	S07176418810209
	259200	PBG958	22/Oct/2013	PROPERTY	MB	0	0	0	HAWKIKG486W3
	2013175203002	PCJ010	14/Oct/2013	INJURY	AB	0	0	0	T02455441501004
	2013030922901	PCR335	8/Oct/2013	INJURY	AB	0	0	0	115431308
	255519	PBG958	23/Sep/2013		MB	1	0	4	HAWKIKG486W3
urisdiction in which	(T)	DDC772	22/14/2012	PROPERTY	AD	0	0	0	TOUREM158MA
he accident occurred.	30472102	PCF754	10/Jul/2013	PROPERTY	PAR I	0	0	2	D27867903690105
	***************************************	PCN882		PROPERTY	12201	0	0	0	DREGEHB363JR
	1791387.1	PCR350	28.038.00V-070.00M-0	PROPERTY		0	0	0	74650264
		PCH692	A CONTRACTOR OF THE PARTY OF TH	PROPERTY	1	0	0	0	403364248520802
	1801905.1	PCF513	9/May/2013	PROPERTY	SK	0	0	0	CHAUHHS310C1