



**Figure 32:** Photos of sediments present at section 15112TH119: **a)** stream-view of the cut exposing sediments; **b)** upper alluvial sediments and contact with anthropogenic diamict fill; **c)** bedded alluvial sediments; **d)** gravel at 2.2 m depth; **e)** lower mottled diamict exposed at the section.